

**True-RMS
Digital Clamp-on AC/DC Multimeter**

Start Here

See User's Guide for detailed instructions.



1/3

① Install two AA batteries (not included)



② Connect the test leads



Red Lead

Black Lead

Package Contents



Multimeter



Carry Case




K-Type Thermocouple



Test Leads (2)



User's Guide



Quick Start

③ Set the function switch and buttons



Function Switch

Set to different functions.

HOLD: Hold a reading.

RANG: Select manual mode and ranges.

ZERO: Zero the meter display.

FUNC: Select a function.

④ Measure AC/DC current



1. Press the trigger to open the clamp.

2. Enclose the conductor; let the front side of the meter face the positive pole of the circuit under test.

3. For DC current, press **ZERO** to zero the meter display first.